




























Montageanleitung

 <p>A=1PC</p>	 <p>B=1PC</p>	 <p>C=1PC</p>	 <p>D=1PC</p>	 <p>E=1PC</p>	 <p>F=1PC</p>
 <p>G=1PC</p>	 <p>H=1PC</p>	 <p>I=1PC</p>		 <p>J=1PC</p>	 <p>K=2PC</p>
 <p>L=1PC</p>	 <p>M=2PC</p>	 <p>N=2PC</p>	 <p>O=2PC</p>		
 <p>R=2PC</p>	 <p>S=2PC</p>	 <p>T=2PC</p>	 <p>U=M3.5*30=16PC</p>		 <p>Y=M3.5*25=8PC</p>
 <p>W=M3.5*20=10PC</p>	 <p>Z=M3*16=8PC</p>	 <p>V=M3*10=6PC</p>		 <p>X=1PC</p>	<p>Z1</p>  <p>Z2</p> 


1



$M+E+D=M3.5*30=4PC$


$M+C+F=M3.5*30=4PC$

2




$L=M3.5*30=4PC$

3



$B+G=M3.5*30=4PC$

4




$H+I=M3.5*25=8PC$

$I+K=M3*10=4PC$

$H+J=M3*10=2PC$


5



$R+N+O=M3.5*20=8PC$

$T=M3*16=8PC$

6



$X=M3.5*20=2PC$

7

